

## Read out Software - Electronic Torque Wrench with Built-in Angle Gauge-eTAC



Content	page
1.) Installation of read out software "Hazet tool"	1
2.) Starting and using the read out software "Hazet tool"	2 to 8



## 1.) Installation of read out software "Hazet tool":

After download run the file HAZETTool\_Setup.exe and follow the instructions to install the software "Hazet tool" on your PC.

During the installation the following error code "Not passed Windows logo testing" may appear. Select "Continue Installation"

*The installation requires administrator privileges. User needs read and write permissions for the installation folder.* 

Turn on the ETAC - wrench and connect the wrench via a USB cable with the PC on which the read out software is installed. The cable has to be connected to the eTAC-wrench with a plug for his "Mini-USB 5-pin" feature.

The ETAC key is detected and automatically starts the driver installation. Select "Install software automatically"

During the installation the following error code "Not passed Windows logo testing" may appear. Select "Continue Installation"

Then the installation of "Hazet ETAC USB Serial Port" starts automatically. Select "Install software automatically"

During the installation the following error code "Not passed Windows logo testing" may appear. Select "Continue Installation"

### 2.) Starting and using the read out software "Hazet tool"

Start "HAZET-Tool" reading software on the PC.

To establish a connection to a PC, change to the menu with "X" and select the "PC connection" menu option with "+".

Press "OK "in the "PC connection" menu option displays "....".





## Start-Screen ► <Setup>

HZ Hazet-Tool - V. 1.002		<b>_ \</b>
12 Hazet-Tool - V. 1.002	HZ Setup ? X Language selection : ENGLISH GERMAN USE port selection :	Contractor Geniales Workcauge SYSTEM 7000 ETAC Digitale Préadsion und Handling neu definient
1010101100100101001010101010101010101010	USB port connected to : COM3 COM3	
	Cancel OK	0101010101010100101010
Connect Wrench	Device is not connected	Setup Exit

<Language selection>



HZ Hazet-Tool - V. 1.002		
		Geniales Workzoug SYSTEM 7000 ETAC
101010	HZ Setup 🤗 ? 🗙	Digitale Präzision und Handling neu definiert
1010101100100101001010101010101010	Language selection : ENGLISH USB port selection : USB port connected to : COM3 COM1 COM3 Comcel OK	101010
		1001010101010100
Connect Wrench	Device is not connected	Setup

## <usb port selection>



page 4 of 8





Read>



view of the values < <Save to File>





Select file type < Save>



## View of measurement in TXT-file, in Editor or MS-Word:

Protocol\_0249226009\_19\_07\_2011\_11u46m.txt - Editor

Datei Bearbeiten Format Ans	sicht <u>2</u>
<pre>####################################</pre>	HAZET ####################################
MEASUREMENT	19
Measurement mode Torque mode Measured torque Date of measurement Time of measurement Duration of measurement Reference working length Schedule	: Torque : displaying : 204,03 Nm : 18.07.2011 : 20:54:45 : 00:00:06 : 38,5 mm : No schedule
MEASUREMENT	20
Measurement mode Torque mode Measured torque Date of measurement Time of measurement Duration of measurement Reference working length Schedule	: Torque : displaying : 147,00 Nm : 18.07.2011 : 20:54:57 : 00:00:07 : 38,5 mm : No schedule
MEASUREMENT	21
Measurement mode Torque mode Measured torque Date of measurement Time of measurement Duration of measurement Reference working length Schedule	: Torque : displaying : 197,18 Nm : 18.07.2011 : 20:55:27 : 00:00:06 : 38,5 mm : No schedule

for example, a simple protocol

#### View of measurement CSV-file, in Editor or MS-Word.

,
MEASUREMENT; Measurement mode; Torque mode; Measured torque; unit; Target torque; unit; Measured angle; unit; Target angle; unit; Snug torque; unit; Date
19;Torque;triggering;204.03;Nm;200.0;Nm;;;;;;18.07.2011;20:54:45;00:00:06;n.OK;2.0;%;38.5;mm;No schedule;No parameter;;;;;;;;;;
20;Torque;triggering;147.00;Nm;150.0;Nm;;;;;;18.07.2011;20:54:57;00:00:07;OK;2.0;%;38.5;mm;No schedule;No parameter;;;;;;;;;;;
21;Torque;triggering;197.18;Nm;200.0;Nm;;;;;;18.07.2011;20:55:27;00:00:06;OK;2.0;%;38.5;mm;No schedule;No parameter;;;;;;;;;;;
22;Torque;triggering;143.05;Nm;150.0;Nm;;;;;;18.07.2011;20:55:42;00:00:06;n.OK;2.0;%;38.5;mm;No schedule;No parameter;;;;;;;;;;
23;Torque;triggering;201.44;Nm;200.0;Nm;;;;;;18.07.2011;20:56:35;00:00:13;OK;2.0;%;38.5;mm;No schedule;No parameter;;No;;;;;;;;
24;Torque;triggering;205.46;Nm;200.0;Nm;;;;;;18.07.2011;20:56:58;00:00:04;n.OK;2.0;%;38.5;mm;No schedule;No parameter;;No;;;;;;;;
25;Torque;triggering;204.60;Nm;200.0;Nm;;;;;;18.07.2011;20:57:10;00:00:03;n.OK;2.0;%;38.5;mm;No schedule;No parameter;;No;;;;;;;;
26;Torque;triggering;198.66;Nm;200.0;Nm;;;;;18.07.2011;20:57:40;00:00:09;OK;2.0;%;38.5;mm;No schedule;No parameter;;No;;;;;;;;



### start the Excel program

▶ import data

# Data View after import and formatting the csv file in excel and using the charting feature of Excel.



